## **Historic, Archive Document**

Do not assume content reflects current scientific knowledge, policies, or practices.



F7692F0

## FOREST PRODUCTS RESEARCH IN PICTURES

NO. 34

## THROUGH DECAY



U. S. FOREST SERVICE
MADISON. WISCONSIN

This is a frame building corner post set directly in the soil without preservative treatment. Although the rest of the structure is good for
many years of service, this post has been so softened by decay that rats
chose to gnaw through the six inches of decayed wood rather than attack
the soil or siding nearby. The failure and telescoping of the post at this
point caused a sagging of the building frame which in turn caused difficulty in opening and closing the sliding door at the left. Except for
heartwood of the more durable species, posts and other wooden members
near or in contact with the ground should be given a good preservative
treatment or at least be end-dipped in hot creosote if more than temporary
service is desired.

A quantity of timber equal to two-thirds the annual growth on all our forests — about 4 billion cubic feet — is used to replace wood destroyed by decay in service every year.

(Photograph by Forest Products Laboratory, U.S. Forest Service)



